Panasonic

INSTRUCTION MANUAL

Electrostatic Sensor Controller

EF-S1C

CME-EFS1C No.0032-47V

Thank you very much for using Panasonic products. Please read this Instruction Manual carefully and thoroughly for the correct and optimum use of this product. Kindly keep this manual in a convenient place for quick reference.




 Never use this product with a device for personnel protection. In case of using devices for personnel protection, use products which meet laws or standards, such as OSHA, ANSI or IEC etc., for personnel protection applicable in each region or country.

1 OUTLINE

- This product can be used in combination with a exclusive sensor head (FF-S1HS) (optional) to monitor electrical potentials on object surfaces
- It can also be used together with an ionizer to check results of charge removal

2 PART DESCRIPTION



3 MOUNTING

How to mount the controller


- 1) Fit the rear part of the mounting section of the controller on a 35mm width DIN rail.
- 2 Press down the rear part of the mounting section of the unit on the 35mm width DIN rail and fit the front part of the mounting section to the DIN rail.

How to remove the controller

- Push the controller forward
- 2 Lift up the front part of the controller to remove it.
- Note: Take care that if the front part is lifted without pushing the controller forward, the hook on the rear portion of the mounting section is likely to break


How to mount the sensor head

- ① Insert the sensor head connector into the inlet until it clicks.
- 2) Fit the cover to the connector.




35mm width DIN rail

4 I/O CIRCUIT DIAGRAM




Note: If using together with an ionizer manufactured by Panasonic, share the 0V line of this product with the ground of the ionizer, and carry out 0-Adjust when doing 0V measurements




<Points to note when using analog output> Because the 0V lines for judgment output and analog output are common, the analog output may vary depending on the load current. In order to satisfy the linearity specifications for the analog output, do not use the judgment output.

5 OPERATION PROCEDURE AND BASIC SYSTEM



Basic system of operation for NAVI mode (For details, refer to 'MINAVI MODE.)




Basic system of operation for PRO mode (For details, refer to 'PPRO MODE.)

- Notes: 1) Judgment output and analog output will become unstable while setting operations are being carried out. After settings have been completed, use in RUN mode.
 - 2) If the power is turned off while settings are being confirmed (while the display is blinking), the settings may not be applied correctly.

6 RUN MODE


• In this mode, the current measurement value and threshold value are displayed, (Note 1) and the threshold value can be set and 0-Adjust, key lock and display value hold and charge removal time measurement operations can be carried out.

Notes: 1) At the time of shipment, the threshold value is set to be displayed in the green (left) digital display. When the symbol display setting is ON (refer to PRO2 mode), a symbol ("-" only) appears in the green (left) digital display.



7 NAVI MODE

• If the MODE key is pressed, the mode can be changed to a different mode.



2) The values that are displayed during RUN mode will vary as shown in the table below depending on the setting for HOLD mode. (A '-' against the displayed value means that

HOLD mode setting		Display value during RUN mode			
Hald off		Threshold value / Measurement value			
Hoid Pb - 1	>	000	50	Threshold value / Peak value	
Hold Pb-2	>	50	-40	+ peak value / - peak value	
HaldPb-3		50	10 110	Peak value / Measurement value	

- 3) If HOLD mode is set to 'P_B- ',', 'P_B-2' or 'P_B-3', the timer function will be automatically set to 'n_{BB}' (no timer), and it will not be possible to change timer operation.
- 4) When charge removal time measurement has been selected, the output operation will be

8 SETTING RANGE

- The threshold value can be set to within the following range.
 - Distance 8 to 20.5mm : +5 \leq +Threshold value \leq +500 (±1 kV range) -5 \geq -Threshold value \geq -500
- Distance 21 to 100mm: $+5 \le +$ Threshold value $\le +1,000$ ($\pm 2 \, \text{kV range}$) $-5 \ge -$ Threshold value $\ge -1,000$ (±2 kV range)
- 0-adjust can be set to within the following range. -200 ≤ Measurement value ≤ +200
- Calibration can be set to within the following range.
- 0.5 ≤ (Display hold value / Current measurement value) ≤ 10
 Distance 8 to 20.5mm: -1,000 ≤ Measurement value ≤ +1,000
- Distance 21 to 100mm: -1,999


 Measurement value


 +1,999

9 PRO MODE


• If 'PRO' is selected in NAVI mode, the mode changes to PRO mode.

Basic system of operation for PRO mode






Note: If a focus has been set for analog output, the resolution will change.




Note: When RUN mode, if no key is pressed for a certain period of time, the digital display will turn off. The display will be restored when a key is pressed.



The data bank can load and save the items that are displayed in '11 FACTORY SETTING

PRO4 mode setting

The display will not change even when the jog switch is operated.



Note: Refer to '10 LIST OF CODE SETTING' when using the code setting function.


PRO6 mode setting Threshold value (Note 1) Window comparator mode (Note 2) Prob out → Threshold value (Note 1) 2-output mode (Output form) Pro6 nonc **⋖** Maana ata Normal close none nie Probinanc - t- in Holo Timing input for hold measurement

Notes: 1) The same threshold value is set for the + threshold value and the - threshold value 2) For window comparator mode, the Select 1 indicator (yellow) will light up. For 2-output mode, the Select 1 indicator (yellow) and the Select 2 indicator (yellow) will light up.

3) The external input signal is used to carry out 0-Adjust each time. To cancel 0-Adjust, press and hold the MODE key for 1 second or more. (It cannot be canceled by means of an

0-Adjust setting input (Note 3)

10 LIST OF CODE SETTING



Green digital display

	First digit		Second digit		Third digit		Fourth digit	
Direct code	Output form (OUT1, OUT2)			Direct code	Response time	Direct code	Analog output focus	
Ĭ.	Normal open	I	Off	Ĭ	20ms	Ĭ	No focus	
-{	Normal close		ON delay		100ms		Focus x2	
Ĭ	_	Ę	OFF delay	Ĭ	200ms	Ĭ	Focus x5	
7		7	ONE-SHOT delay	11.	400ms	717	Focus x10	
ń		丩	Charge removal time measurement	_C	800ms	7-	_	
Ĭ	_	5	_	5	10ms	Ĭ	_	

Red digital display

First digit		Second digit		Third digit		Fourth digit			
Direct code	Hysteresis function	Direct code	HOLD mode (Note)	External input	Direct code	CUST mode display function	Direct code	Output mode	
Ĭ	2%	Ĭ	No hold		Ĭ	Calibration	Ĭ	Window comparator	
	2%	1	Peak ①	Timing input	-{	Response time change function		2-output	
Ĭ	4%	Į	Peak ②	for hold measurement	į	Analog output focus	į	_	
7	4%	3	Peak ③		3	Data bank loading function	3	_	
丩	1%	丩	No hold		丩	Code setting function	丩	_	
5	1%	5	Peak ①	0-Adjust	5	_	Ę	_	
Ü	0.2%	Ē	Peak ②	input	Ē	_	Ü	_	
7	0.2%	7	Peak ③		7	_	7	_	
Ä	0.5%	8	_		8	_	H	_	
ij	0.5%	3	_		9	_	ij	_	

:The highlighted line indicates the default code (factory setting).

Note: If timer operation and HOLD mode have been set simultaneously, HOLD mode will take priority, and timer operation will be set to 'without timer

11 FACTORY SETTING

 $\ \, \bullet \,$ The default settings (factory settings) for this product are listed below. The settings can be reset to the default settings (factory settings) using setting reset in PRO mode. For details, refer to 'PRO MODE/ PRO5 mode setting'.

NAVI mode

	Hama	Initial potting colum	Digital display		
	Item	Initial setting value	Green	Red	
Threshold	+ potential (OUT1)	100	P. St	(7) (1) (1) (1)	
value	- potential (OUT1)	-100	-,51	- (00)	
0-Adjust		No 0-Adjust	ភាព ប្រជ	/ Measurement value /	
DIST mode		±1kV range, Setting distance 8mm	1d5t	8.0	
HOLD mode		Hold OFF	Hald	gFF	
TIM⊞Rmode		Without timer	ngn		
CUST mode		Calibration	[816	SEE	

PRO mode

Timing chart

ltem	Initial cotting value	Digital display		
item	Initial setting value	Green	Red	
Response time change function	20ms	5060	50	
Hysteresis function	2% of ± 1kV range (20)	H45	#-56	
Calibration	Without calibration (x1)	(Measurement) value	Expected value	
Analog output focus	Without focus (x1)	FeuS	F-[] {	
Display turning	OFF	էսո	g££	
ECO mode setting	OFF	Eco	off	
Code setting function	0000 0000	0000	0000	
Output mode	Window comparator mode	նսե		
Output form	Normal open	none	0.0	
Symbol display setting	OFF	Fuնo	off	
Display unit setting	Displayed up to 1st line (1)	46. E		
External input setting	Timing input for hold measurement	£- In	Ho ld	

12 TIMER FUNCTION

- Identical timer operations (ON delay, OFF delay, ONE-SHOT delay) and timer periods can be set for OUT1 and OUT2.
- The timer period can be set in units of 1ms up to a maximum of 9.999ms
- Timer functions cannot be set while HOLD mode is set.
- If HOLD mode is set after timer function has already been set, the timer will be automatically set to 'กุญกู่ (without timer).

(T:1 to 9,999ms)

• For details on the timer function setting method, refer to 'TNAM MODE

· Norma	open	
Normal operation	ON OF	
ON delay timer	→ T ← ON OF	
OFF delay timer	T T T ON OFF	
ONE-SHOT delay timer	T T T T T T T T T T T T T T T T T T T	
· Norma	close	
Normal operation	OFF OFF	
ON delay timer	→ T ←	
OFF delay timer	→ T ← ON OFF	
ONE-SHOT delay timer	T T T T T T T T T T T T T T T T T T T	

B ERROR DISPLAY

Take the following actions in case of errors.

Display	Output operation	Description of error	Action		
Er- (Cvercurrent has be due to short-circu		Turn off the power supply and check the load.		
H_Ou	H_ au OU12:ON Analog:5V + potential is outside the range. OUT2:ON Disconnection error in sensor head, or - potential is outside the range.		If using the ±1kV range, set the measurement distance to 21mm or more, and use the ±2kV range.		
Lou			If the error is not cleared when measuring at 0V, the problem is a disconnection error. Check the connection status for the sensor head. If the error is cleared when measuring at 0V, the - potential is outside the range. Set the measurement distance to 21mm or more, and use the +2kVrange.		
OAdu Err	_	The setting exceeds the 0-Adjust setting range.	Cancel 0-adjust and check the measurement values.		

Note: If OUT2 is used for over-range output, the output mode must be set to window comparator

14 MAJOR SPECIFICATIONS

Designa	ion Bectrostatic sensor controller
Item Model	
Applicable sensor head	EF-S1HS
Supply voltage	24V DC±10%
Current consumption	Normal operation: 50mA or less, ECO mode: 40mA or less
Measurement distance (measurement range)	8 to 20.5mm (±1kVrange), 21 to 100mm (±2kVrange) (Note 1)
Repeatability	±0.3%FS (Note 2)
Linearity	±0.5%FS (Note 2, 3)
Temperature characterist	cs 0.05%FS./ °C (Note 4)
Judgment output (OUT1, OUT2)	NPN open-collector transistor • Maximum sink current: 100mA • Applied voltage: 30V DC or less (between judgment output and 0V) • Residual voltage: 1.5V or less (at 100mA sink current)
Response time	10ms/ 20ms/ 100ms/ 200ms/ 400ms/ 800ms
Output operation	OUT1:+ judgment output or window comparator output OUT2:- judgment output or error output
Short-circuit protect	ion Incorporated
Analog output (Note 5	 Output voltage:+1 to +5V Output impedance: 100 Ω approx.
Response time	20ms/30ms/110ms/210ms/410ms/810ms
Timing input	NPN non-contact input • Sgnal condition: High: +V, or open Low: 0 to +2V (source current 0.5mA) • Input impedance: 10k Ω approx.
Ambient temperature	-10 to +55°C (No dew condensation or icing allowed), Storage: -20 to +70°C
Ambient humidity	35 to 85% RH, Storage: 35 to 85% RH
Material	Enclosure: Heat-resistant ABS, Transparent cover: Polycarbonate Press switches: Acrylic, Jog switch: Heat-resistant ABS
Cable	0.2mm ² 6-core cabtyre cable, 2m long
Weight	65g approx.

measurement distance and use at a fixed distance. The measurement distance can be set at a pitch of 0.5mm (distances of 40 mm or more are at 1 mm pitch).

- 2) The repeatability precision and linearity values given are those for no calibration and no analog output focus.
- 3) The values given are for when the measured value is ± 200 V in the ± 1 kV range and \pm 400V in the $\pm 2 k$ V range. If the measured values are outside these values, the values will be equal to the displayed values $\pm 5\%$.
- 4) The values given are when used together with the exclusive sensor head The values given are for when the measured value is ± 200 V in the ± 1 kV range and \pm 400V in the ±2kV range. If the measured values are outside these values, the values will be 0.5%/ °C of the displayed values.
- 5) In order to satisfy the linearity specifications for the analog output, do not use the judgment 6) F.S. is 2,000 for the ±1kV range and 4,000 for the ±2kV range.

15 CAUTIONS

- This product has been developed / produced for industrial use only.
- Make sure that the power supply is off while wiring.
- Verify that the supply voltage variation is within the rating.
- Take care that if a voltage exceeding the rated range is applied, or if an AC power supply is directly connected, the sensor may get burnt or damaged.
- In case noise generating equipment (switching regulator, inverter motor, etc.) is used in the vicinity of this product, connect the frame ground (F.G.) terminal of the equipment to an actual ground.
- If power is supplied from a commercial switching regulator, ensure that the frame ground (F.G.) terminal of the power supply is connected to an actual ground.
- Do not use during the initial transient time (3 sec.) after the power supply is switched on. • In order for stable sensing to be carried out, wait for 10 minutes after turning on the
- power before use. ■ Take care that short-circuit of the load or wrong wiring may burn or damage the sensor.
- There is no short-circuit protection circuit for analog output installed. Do not connect the power supply or capacity load directly. • Do not run the wires together with high-voltage lines or power lines or put them in
- the same raceway. This can cause malfunction due to induction
- Extension up to total 10m is possible with 0.15mm², or more, cable. However, in order to reduce noise make the wiring as short as possible
- This sensor is suitable for indoor use only.
- Avoid dust, dirt, and steam.
- Take care that the product does not come in direct contact with water, oil, grease, or organic solvents, such as, thinner, etc.
- This sensor cannot be used in an environment containing inflammable or explosive gases.
- Never disassemble or modify the sensor.

16 INTENDED PRODUCTS FOR CE MARKING

● The models listed under " SPECIFICATIONS" come with CE Marking.

As for all other models, please contact our office.

Contact for CE

<Until June 30 ,2013>

Panasonic Industrial Devices Sales Central Europe AG Rudolf-Diesel-Ring 2, D-83607 Holzkirchen, Germany

<From July 1 ,2013>

Panasonic Marketing Europe GmbH Panasonic Testing Center Winsbergring 15, 22525 Hamburg, Germany

Panasonic Industrial Devices SUNX Co., Ltd.

http://panasonic.net/id/pidsx/global

Overseas Sales Division (Head Office) 2431-1 Ushiyama-cho, Kasugai-shi, Aichi, 486-0901, Japan

Phone: +81-568-33-7861 FAX: +81-568-33-8591

About our sale network, please visit our website. PRINTED IN JAPAN

© Panasonic Industrial Devices SUNX Co., Ltd. 2012